

Log

PATENT

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence for Patent Application No. 09/986,499 is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on October 17, 2005.

David W. Dorton, Registration No. 51,625

OCTOBER 17, 2005

Date

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,810,635 B2
Issue Date: November 2, 2004
Applicant: Steven R. Meizlish
Application No: 09/986,499
Filed: November 9, 2001
Title: **AUTOMOTIVE WINDOW TRIM MOLDING**
Art Unit: 3635
Confirmation No: 5584
Examiner: Carl D. Friedman
Atty. Docket No: MAEI-06

Certificate
OCT 24 2005
of Correction

Cincinnati, Ohio 45202

October 17, 2005

Certificates of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R. §1.322(a))**

Applicant respectfully requests correction of the errors in the above-identified letters patent, in accordance with 37 C.F.R. §1.322(a)(1)(i).

Attached, in duplicate, is Form PTO-1050 (Substitute Form PTO76-22), with at least one copy being suitable for printing.

OCT 25 2005

The exact page and line number where the errors are shown correctly in the application file are:

Column 5, line 58, claim 1, reads "...a third sidewall extending from/an end of..." and should read – ...a third sidewall extending from an end of... – .

Column 8, line 17, claim 24, reads "...prior to fining the trim molding to..." and should read – ...prior to fitting the trim molding to... – .

Making Errors of Record

The following printing errors have been noted in the above-identified issued patent. The errors do not appear to be of sufficient importance to warrant a Certificate of Correction, but by this letter are made of record.

Column 2, line 31, reads "...around the peripheral edge of the glass panel to bond to the molding to the glass panel,..." and should read -- ...around the peripheral edge of the glass panel to bond the molding to the glass panel,... --.


Column 2, lines 38, reads "The preferred embodiments, taken in conjunction with the accompanying drawings." This is an incomplete sentence and should be deleted.

It is noted that the errors that appear in this patent are of a typographical nature or character, as more fully described above, and occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination. A certificate of correction is respectfully requested.

Please send the certificate to the undersigned. If any other charges or credits are necessary to complete this communication, please apply them to Deposit Account 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By: 
David W. Dorton
Reg. No. 51,625

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati OH 45202
(513) 241-2324
(513) 421-6234 facsimile

Staple
Here
Only

Printer's
Trim
Line

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,810,635 *B2*

Page 1 of 1

DATED : November 2, 2004

INVENTOR(S) : Steven R. Meizlish

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5

Line 58, claim 1, reads "...a third sidewall extending from/an end of..." and should read –
...a third sidewall extending from an end of... – .

Column 8

Line 17, claim 24, reads "...prior to fining the trim molding to..." and should read –
...prior to fitting the trim molding to... – .

MAILING ADDRESS OF SENDER:

WOOD, HERRON & EVANS, L.L.P.
2700 Carew Tower, 441 Vine Street
Cincinnati, Ohio 45202

SUBSTITUTE FORM PT076-22

PATENT NO. 6,810,635

No. of add'l copies
@ 50¢ per page

OCT 25 2005